


Quick Draw Soilmoisture Probes

The Model 2900F1 Quick Draw Tensiometer is designed for portable field use. It responds quickly and equilibrates rapidly with the tension in the soil, providing measurements within a few minutes. The Soil Coring Tool is first used to core an access hole to the desired depth of measurement. The tensiometer is then inserted into the access hole and the ceramic sensing tip is placed in contact with the soil. The Null Knob can be used to reach equilibrium and provide a measurement more rapidly. The coring tool, cleaning tool, and tensiometer are then returned to the carrying case for transportation and storage. An accessory kit, which contains a replacement ceramic sensing tip, O-rings, screwdriver, and Allen wrench, is included.



Ordering information

2900F1L12	Quick Draw Soilmoisture Probe, 12" (30 cm) length
2900F1L18	Quick Draw Soilmoisture Probe, 18" (46 cm) length
2900F1L24	Quick Draw Soilmoisture Probe, 24" (61 cm) length

Replacement parts

2900FK1	Accessory Kit, includes replacement sensing tip, screwdriver, O-rings, Allen wrench
2901-002K1	Replacement Sensing Tip, includes ceramic sensing tip and 2 O-rings.
2060FG5	Replacement dial gauge
2900FK2	O-ring kit (includes 1 x O-ring for all parts of Quick Draw)



ICT International Pty Ltd

PO Box 503
Armidale NSW 2350
AUSTRALIA

Ph: [61] 2-6772-6770
Fax: [61] 2-6772-7616

sales@ictinternational.com.au
www.ictinternational.com.au